



ARDON®
WORKWEAR
& OUTDOOR

ARDON® SIGNAL

SWEATSHIRT



TECHNICAL DATA SHEET



REFLECTIVE



BREATHABLE



WINDPROOF



**3D
SILHOUETTE**



DRY AIR



ARDON[®]
WORKWEAR
& OUTDOOR

ARDON[®] SIGNAL

SWEATSHIRT

ITEM CODE H5929 (yellow-orange)
H5956 (yellow-black)
H5967 (orange-black)

MATERIAL 65 % polyester, 35 % cotton

GRAMMAGE 300 g/m²

ADDITIONAL MATERIAL softshell (94% polyester, 6% spandex),
310 g/ m2

SIZE H5929 S – 4XL
H5956 XS – 5XL
H5967 XS – 5XL

DESCRIPTION

Designed sweatshirt with reflective stripes (2 on the body, 2 on the arms), additional reflective stripes on the shoulders to increase the safety of the wearer, flexible knit on the sleeves and bottom hem, 2 zipped pockets. Hi-vis sweatshirt is a must-have for any job that requires you to be visible at night or in low-light conditions.

This personal protective equipment is in conformity with these harmonized European Standards:

EN ISO 13688:2013 – Protective clothing - General requirements.

EN ISO 20471:2013/A1:2016 – High visibility clothing – Test methods and requirements.

Certified by notified body no. 1021 (Textilní zkušební ústav s.p., Brno, Czech Republic), **Certificate number 1021 – 20 - 100, dated 2nd of December 2020 and 1021 – 23 – 027 dated 14 of April 2023.**

TECHNICAL DATA SHEET

**ARDON®****WORKWEAR
& OUTDOOR**

PIECES IN CARTON	20 pcs
CARTON WEIGHT	16 kg
CARTON SIZE	0,182 m ³
UNIT PACKAGING (POLYBAG)	1 pc

Service life depends on the frequency of use and the wear rate under the given conditions. Improper storage and improper maintenance and handling will reduce the service life. The warranty period is 24 months. In no event may the warranty period be confused with a product's service life. Under intense use, the service life may be shorter than the warranty period. The product contains no substances at concentrations that are known or suspected to have adverse effects on sanitation or a user's health. However, skin irritation may occur with sensitive persons; in this case, the discontinue use of the clothing. Avoid fire and intense heat sources. There are no designated accessories or spare parts for this clothing. When a garment is not being worn, it should be stored in dry and well ventilated places out of direct sunlight. In order to transport, the original packaging should be used. Protect from moisture and extreme temperatures. After use, dispose of in an environmentally friendly manner





ARDON®
WORKWEAR
& OUTDOOR

TECHNICAL DATA SHEET

