

TECHNICAL DATA SHEET

M007

Workwear/Outdoor

Article NO: H5940 (black)
H5941 (dark blue)
H5943 (green)
H5944 (brown)
H5946 (dark grey)
H5947 (bright red)
H5948 (white)
H5951 (middle royal blue)



Material: 50% cotton,
50% polyester

Grammage: 340 g/ m²



Size: H5940, H5948, H5951, H5944: XS - 5XL
H5941, H5943, H5947: S - 4XL
H5946: XS - 4XL

A men's sweatshirt with a fit cut and a stand up collar; a majority percentage of cotton for a pleasant wear; a trendy combination of materials; shoulders reinforced with knitted fabric; shaping seams; zipper; 2 hidden bottom pockets; a wide selection of colour combinations.

This personal protective equipment is in conformity with these harmonized European Standards:

EN ISO 13688:2013 : Protective clothes - General requirements.

PPE of the simple construction against minimal risk, which can be recognized by the user safely at an early stage.

Self certification have been performed on the base of technical documentation of the PPE and practical exams of the ergonomic features of the PPE by the Ardon



Safety s.r.o. company, dated 14th October 2020.

Collection M007 meets the requirements for medical harmlessness and is certified according to STANDARD 100 by OEKO-TEX®, certificate no. PG020 198789



Pieces in carton:	15
Carton weight:	13,0 kg
Carton size:	0,075 m ³
Polybag packing (pieces):	1

Service life depends on the frequency of use and the wear rate under the given conditions. Improper storage and improper maintenance and handling will reduce the service life. The warranty period is 24 months. In no event may the warranty period be confused with a product's service life. Under intense use, the service life may be shorter than the warranty period.

The product contains no substances at concentrations that are known or suspected to have adverse effects on sanitation or a user's health. However, skin irritation may occur with sensitive persons; in this case, the discontinue use of the clothing. Avoid fire and intense heat sources. There are no designated accessories or spare parts for this clothing. When a garment is not being worn, it should be stored in dry and well ventilated places out of direct sunlight. In order to transport, the original packaging should be used. Protect from moisture and extreme temperatures. After use, dispose of in an environmentally friendly manner.
