

TECHNICAL DATA SHEET

HYBRID

Workwear

Article NO:

H5952 (black) H5953 (dark grey) H5954 (dark blue) H5955 (khaki) H5957 (brown) H5958 (red)



Outer shell: Lining: 90 % nylon, 10 % spandex 100 % polyester

Grammage: 370 g/ m²

Size:

XS - 5XL (H5952), S - 4XL (other colorways)

A men's winter bomber jacket with a stand-up collar, insulated with warm fur; an interesting cut with accentuated shoulders and upper arms for a slimmer cut; designer seams on the front shoulder, sleeves and sides; a combination of materials; zipper; shaping seams on the front and on the back; chest zippered pocket; 2 bottom zippered pockets; ribbed knitted fabric on the bottom sleeve edges and the bottom jacket edge.

This personal protective equipment is in conformity with these harmonized European Standards:

ČSN EN ISO 13688:2013 : Protective clothes - General requirements. PPE of the simple construction against minimal risk, which can be recognized by the user safely at an early stage.

Self certification has been performed on the base of technical documentation of the PPE and practical exams of the ergonomic features of the PPE by the Ardon Safety s.r.o. company, dated 4th November 2020.

Pieces in carton:	10
Carton weight:	10,5 kg
Carton size:	0,075 m ³
Polybag packing (pieces):	1



Service life depends on the frequency of use and the wear rate under the given conditions. Improper storage and improper maintenance and handling will reduce the service life. The warranty period is 24 months. In no event may the warranty period be confused with a product's service life. Under intense use, the service life may be shorter than the warranty period.

The product contains no substances at concentrations that are known or suspected to have adverse effects on sanitation or a user's health. However, skin irritation may occur with sensitive persons; in this case, the discontinue use of the clothing. Avoid fire and intense heat sources. There are no designated accessories or spare parts for this clothing. When a garment is not being worn, it should be stored in dry and well ventilated places out of direct sunlight. In order to transport, the original packaging should be used. Protect from moisture and extreme temperatures. After use, dispose of in an environmentally friendly manner.