

TECHNICAL DATA SHEET

COOL TREND BLOUSE

Workwear

Article NO: H8100 (blue)
H8103 (green)
H8106 (red)
H8204 (grey-black)
H8208 (grey-orange)
H8220 (blue-blue)
H8800 (white-grey)
H8950 (seaport blue)
H8957 (fondue brown)
H8964 (black)



Women´s: H8190 (blue-black)
H9132 (grey-orange)
H8193 (green-black)

Material: 100% cotton
Grammage: 260 g/ m²

Men´s size: S - 5XL
H8100, H8220: XXS - 7XL

Women´s size: XS - 5XL



Men´s and women´s blouse from high quality material.

Description: two upper pockets with velcro fastening, one upper pocket for cell phone with zipper, reflective stripes

This personal protective equipment is in conformity with these harmonized European Standards:

ČSN EN ISO 13688:2013: Protective clothes - General requirements.

PPE of the simply construction against minimal risk, which can be recognized by the user early and safely.

Self certification have been performed on the base of technical documentation of the PPE and practical exams of the ergonomic features of the PPE by Ardon Safety s.r.o. company, dated 17th of December 2020.



Collection Cool Trend meets the requirements for medical harmlessness and is certified according to STANDARD 100 by OEKO-TEX®, certificate no. PG020 128167 OETI.



Pieces in carton:	20
Carton weight:	18 kg
Carton size:	0,063 m ³
Polybag packing (pieces):	1

Service life depends on the frequency of use and the wear rate under the given conditions. Improper storage and improper maintenance and handling will reduce the service life. The warranty period is 24 months. In no event may the warranty period be confused with a product's service life. Under intense use, the service life may be shorter than the warranty period.

The product contains no substances at concentrations that are known or suspected to have adverse effects on sanitation or a user's health. However, skin irritation may occur with sensitive persons; in this case, the discontinue use of the clothing. Avoid fire and intense heat sources. There are no designated accessories or spare parts for this clothing. When a garment is not being worn, it should be stored in dry and well ventilated places out of direct sunlight. In order to transport, the original packaging should be used. Protect from moisture and extreme temperatures. After use, dispose of in an environmentally friendly manner.
